U.S. EPA Region 6 Operational Period: DAILY WORK ORDER Site Name: 2-20-2015 mergency and Rapid Response Service Task Order 62 CES Environmental Date: Division/ Response Federal Group: Branch: WORK AUTHORIZED: Continue to pump water on site as necessary, depending on rainfall. Continue development of profiles and disposal of sludge, liquids, and solids. Continue removal of water, oil, sludge, and waste, from the ASTs, Frac Tanks, Totes, and Drums. ERRS Response Manager On-Scene Coordinator: TXD 008950461 Site Cerclis:# LeRoy Cassidey, CB&I Federal EP - S6 - 07 -02 Gary Moore, USEPA Time: 1700 Contract Number: Date: 2.20.2015 Time:1700 Date: 2.20.2015 062 Task Order: EQUIPMENT ON-Unused USED OTY Unused Used QTY SITE: PERSONNEL ON-SITE: 3 3 Pick -up Truck 1 Response Manager 1 1 Generator 1 1 Foreman 0 0 Trash Pumps 0 0 1 1 PID 1 Truck Driver/Equip Op 1 Frac Tank w Liner 1 1 3 3 Laborer 4,000 PSI Pressure 1 1 0 Washer Health and Safety Manager 0 8 8 Open Top Roll Off PERSONNEL OFF-SITE 1 Vacuum Truck Air Mover 1 1 1 Subcontract Manager 1 1 Carbon Vapor Unit 1 1 Transport and Disposal Coord 1 1 Skid Steer 1 Field Cost Accountant 1 25 25 Vacuum Boxes 1 9,000 lb Overhead Lift 1 1 1 Storage Trailer 1 Myers (Bean) Pump 1 1 1 Air Compressor

WORK ACCOMPLISHED / AMENDMENTS (problem areas, general comments, summary )(Input for day's 1, 900-5Pon5):

The RM discussed the remaining tank waste and the drums/totes bulking schemes with the OSC, T&D Coordinator, and Foreman. Continued to processed invoices, operational-H/Safety paperwork and update status spreadsheets. Continue to provide information to CB&I for their TCEQ proposal modifications.

T&D Coordinator continued developed of sampling/bulking schemes, scheduling for transportation and disposal of totes, drums, and small container waste. Continue discussion on remaining waste with the OSC and RM.

Crew continued sludge removal from the WWT Tanks T10, T11, T13 and T 12. Crew secured site for weekend

Time: 0830 Date: 2.23.2015 Time: 2/23/15 1254

Next OPERATIONAL PERIOD (administrative, tactical / resource status changes, special instructions, H&S)(Input for next DWO):

Clean Frac Tank FT 1001, FT 5180.

Start removal of water and sludge from PT 4. Break/drain lines in WWT area.